

	Type	Hits	Search Text	DBs
1	BRS	5	6,246,558	USPAT; US-PGPUB
2	BRS	6	6,282,070	USPAT; US-PGPUB
3	BRS	0	6,0040,967	USPAT; US-PGPUB
4	BRS	25	6,040,967	USPAT; US-PGPUB
5	BRS	230	ground adj fault same filter	USPAT; US-PGPUB
6	BRS	18	ground adj fault same filter same transient	USPAT; US-PGPUB
7	BRS	12	ground adj fault same filter same surge	USPAT; US-PGPUB
8	BRS	1	ground adj fault same filter same MOV	USPAT; US-PGPUB
9	BRS	3	ground adj fault same filter same (MOV varistor)	USPAT; US-PGPUB
10	BRS	6	ground adj fault same filter same (LC capacitor adj inductor)	USPAT; US-PGPUB
11	BRS	12	ground same fault same filter same (LC capacitor adj inductor)	USPAT; US-PGPUB
12	BRS	6	5,892,667	USPAT; US-PGPUB
13	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
14	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
15	BRS	4	6088205.URPN.	USPAT
16	BRS	2630	361/111	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	1054	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
1	2004/08/10 12:25			0
2	2002/10/14 14:51			0
3	2002/10/14 14:51			0
4	2002/10/14 14:58			0
5	2002/10/14 15:19			0
6	2002/10/14 14:59			0
7	2002/10/14 15:26			0
8	2002/10/14 15:26			0
9	2002/10/14 15:28			0
10	2002/10/14 15:31			0
11	2002/10/14 16:02			0
12	2002/10/14 15:36			0
13	2002/10/14 15:42			0
14	2002/10/14 15:46			0
15	2002/10/14 15:52			0
16	2002/10/14 16:03			0
17	2002/10/15 09:38			0

	Type	Hits	Search Text	DBs
18	BRS	38	(mov varistor) same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	0	sparc adj gap same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	0	sparc adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	0	sparc adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	0	sparc same gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	4	spark adj gap same filter same LC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	184	spark adj gap same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	351	Leviton adj Manufacturing	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	68	Leviton adj Manufacturing and ground same fault	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	4	Leviton adj Manufacturing and ground same fault same LC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	23	("4376243" "4466071" "4658322" "4709293" "4878144" "5185684" "5202662" "5206596" "5223795" "5224006" "5280404" "5432455" "5434509" "5459630" "5561505" "5590012" "5715125" "5805397" "5805398" "5815352" "5818237" "5835321" "5847913").PN.	USPAT
29	BRS	1054	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	935	361/93.6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
31	BRS	12	5,617,284	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
18	2002/10/15 12:18			0
19	2002/10/15 12:19			0
20	2002/10/15 12:19			0
21	2002/10/15 12:20			0
22	2002/10/15 12:20			0
23	2002/10/15 12:21			0
24	2002/10/15 12:42			0
25	2002/10/15 12:42			0
26	2002/10/15 12:42			0
27	2002/10/15 12:53			0
28	2002/10/15 12:45			0
29	2002/10/15 12:55			0
30	2002/10/15 14:18			0
31	2002/10/15 15:24			0

	Type	Hits	Search Text	DBs
32	BRS	16	ground same fault same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	9	ground adj fault same LC same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	64	ground adj fault same (mov varistor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	5	ground adj fault same (mov varistor) same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	160	ground adj fault same (solenoid coil) same capacitor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	34	ground adj fault same (solenoid coil) same capacitor same filter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
38	BRS	573	361/85	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
39	BRS	64	(mov varistor) same bypass same capacitor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	37	5,448,443	USPAT; US-PGPUB
41	BRS	30	5,448,443 and filter	USPAT; US-PGPUB
42	BRS	243	filter same mov	USPAT; US-PGPUB
43	BRS	0	filter adj (protect protecting) adj mov	USPAT; US-PGPUB
44	BRS	0	filter adj (protect protecting) same mov	USPAT; US-PGPUB
45	BRS	2	filter adj2 (protect protecting) same mov	USPAT; US-PGPUB
46	BRS	0	filter near (protect protecting) same mov	USPAT; US-PGPUB
47	BRS	3	filter near2 (protect protecting) same (mov surge adj protector)	USPAT; US-PGPUB
48	BRS	3	filter near2 (protect protecting) same (mov or surge adj protector)	USPAT; US-PGPUB
49	BRS	8	filter near2 (protect protecting) same (mov or surge adj protector suppressor)	USPAT; US-PGPUB
50	BRS	15	4,275,739	USPAT; US-PGPUB
51	BRS	185	solenoid adj coil same zener	USPAT; US-PGPUB
52	BRS	51	solenoid adj coil same zener same series	USPAT; US-PGPUB
53	BRS	2965	361/111	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
32	2002/10/15 15:26			0
33	2002/10/15 15:29			0
34	2002/10/15 15:30			0
35	2002/10/15 15:59			0
36	2002/10/15 16:03			0
37	2002/10/15 16:04			0
38	2002/10/15 17:16			0
39	2002/10/16 11:15			0
40	2004/02/05 14:09			0
41	2004/02/05 14:19			0
42	2004/02/05 14:19			0
43	2004/02/05 14:20			0
44	2004/02/05 14:20			0
45	2004/02/05 14:22			0
46	2004/02/05 14:22			0
47	2004/02/05 14:24			0
48	2004/02/05 14:24			0
49	2004/02/05 14:30			0
50	2004/02/05 14:46			0
51	2004/02/05 14:49			0
52	2004/02/05 14:49			0
53	2004/02/05 15:25			0

	Type	Hits	Search Text	DBs
54	BRS	37951	(mov spark) same parallel zener	USPAT; US-PGPUB
55	BRS	34588	(mov spark) adj parallel zener	USPAT; US-PGPUB
56	BRS	0	mov adj parallel adj zener	USPAT; US-PGPUB
57	BRS	0	mov adj2 parallel adj2 zener	USPAT; US-PGPUB
58	BRS	1	mov same parallel adj2 zener	USPAT; US-PGPUB
59	BRS	0	mov near2 parallel adj2 zener	USPAT; US-PGPUB
60	BRS	0	mov near2 parallel near2 zener	USPAT; US-PGPUB
61	BRS	1	spark near2 parallel near2 zener	USPAT; US-PGPUB
62	BRS	28	spark same parallel near2 zener	USPAT; US-PGPUB
63	BRS	207	spark same parallel near2 resistor samezener	USPAT; US-PGPUB
64	BRS	31	spark same parallel near2 resistor same zener	USPAT; US-PGPUB
65	BRS	1132	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
66	BRS	1132	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
67	BRS	2	3,731,154	USPAT; US-PGPUB
68	BRS	3	("3515934" "3513354" "3348100").PN.	USPAT
69	BRS	3106	361/111	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
70	BRS	977	361/93.6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
71	BRS	1158	361/79	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
72	BRS	587	361/113	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
54	2004/02/05 16:05			0
55	2004/02/05 16:06			0
56	2004/02/05 16:06			0
57	2004/02/05 16:06			0
58	2004/02/05 16:06			0
59	2004/02/05 16:06			0
60	2004/02/05 16:07			0
61	2004/02/05 16:08			0
62	2004/02/05 16:08			0
63	2004/02/05 16:09			0
64	2004/02/05 16:20			0
65	2004/02/05 16:21			0
66	2004/02/06 09:28			0
67	2004/02/06 09:58			0
68	2004/02/06 09:58			0
69	2004/08/09 13:56			0
70	2004/08/09 15:36			0
71	2004/08/10 09:02			0
72	2004/08/10 12:25			0